



## Window Touch Up Procedure

### Carbon Dark Cap Stock

MANY MARKS CAN BE REMOVED WITH A MAGIC ERASER. PLEASE SEE YOUR CUSTOMER SERVICE OR SALES REPRESENTATIVE FOR MORE INFORMATION.

- Ensure the affected area is clean and free of any loose debris, dirt or other contaminants.
- Use the paint pen small amount of paint to the area. Do not over apply or blemished area may be magnified.
- Wait 15 minutes for the first coat to dry.
- Apply and blend a second coat if needed.





Chip / Scratch

Chip /Scratch after touch-up.